


GUIDE TO APPAREL/ TEXTILE CARE SYMBOLS

 Wash	Machine Wash Cycles						
	Water Temperatures	Normal (Max) (20C) Symbols	Perm Press (20F) (60C) Symbols	Delicate Gentle (16F) (6C) Symbols	(14F) (5C) Symbols	(12F) (5C) Symbols	(10F) (4C) Symbols

 Bleach		
	Any Bleach When Needed	Only Non-Chlorine Bleach When Needed

 Dry	Tumble Dry Cycles				
	Tumble Heat Settings				
					
	Line Dry/ Hang to Dry	Drip Dry	Dry Flat		

 Iron	Iron - Dry or Steam			
	Maximum Temperatures	200C (390F) High	150C (300F) Medium	110C (230F) Low

 Dryclean	Dryclean - Normal Cycle				Dryclean - Additional Instructions	
		Any Solvent	Any Solvent Except Trichloroethylene	Petroleum Solvent Only		
		Do Not Dryclean		Reduced Moisture		No Steam Finishing

Warning Symbols for Laundering	
	
Do Not Wash	Do Not Iron
	
Do Not Bleach	Do Not Dry (Used with Do Not Wash)

Additional Instructions (in Symbols or Words)	
	
Do Not Tumble Dry	Do Not Wring
	
In the Shade (added to line dry, drip dry or dry flat)	No Steam (added to iron)